

FD1

Fused Distribution Board

INTRODUCTION

The FD1 Distribution Board is used to provide 4 fused outputs from a single power source. The module accepts any voltage at terminals PWR and will split this into 4 outputs via individual 1A fuses to power auxiliary equipment.

CONNECTION

Terminal (PWR) Connection for power supply please observe polarity.

Terminal (F1,F2,F3 ,F4) 1A Fused outputs

SPECIFICATION

Dimensions 90 x 50 mm.

Input Voltage AC or DC.

Output 4 x 1A Fused outputs

WIRING

